



**AUDI Q5: 1LAB614**

Vinnumber:	<b>WAUZZZ8RXGA020746</b>	Versionname:	<b>2.0 TDI 110KW</b>
First Registrationdate:	<b>30/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>166024</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Rims summer:	<b>Aluminium</b>
Transmission:	<b>Front</b>	Oil level:	<b>OK</b>
Fueltype:	<b>Diesel</b>	Parking lot:	<b>4514</b>
Maintenance:	<b>OK</b>		
Maintenance:	<b>OVER 14800 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total:	<b>2</b>	Sun Roof electric:	
Number keys remote:	<b>2</b>	Panoramic roof:	
Radio CD:		Central consol F:	
GPS storage:		Luggage cover:	
GPS storage:	<b>HD</b>	Front parking sensors:	
Windows electric F:		Rear parking sensors:	
Windows electric R:		Type of Tow bar:	<b>Tow bar collapsible</b>
Cruise Control:			
Steering wheel multifunctional:			
Seats F heated:			
Type of headlighting:	<b>Headlighting Xenon</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining leather</b>		
Type of climate control:	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning:	<b>OK</b>	Battery functioning:	<b>Yes</b>
Tires wear profile:	<b>OK</b>	Power steering:	<b>Yes</b>
Idle position:	<b>OK</b>	Sound engine:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Clutch test:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Wiper fluid level:	<b>OK</b>
Handbrake:	<b>OK</b>	Transmission:	<b>OK</b>
		Lighting:	<b>OK</b>
		Wiperblades:	<b>OK</b>

**Degree of wear**

<b>235/65/17/108 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Total cost ex VAT:			<b>870,82</b>
Windscreen, Stone chip(s), E - Replace:			<b>629,70</b>



Door RR, Scratch(es), Acceptable 0,00

No pictures to display

Inner door sill FL, Scratch(es), Acceptable 0,00

No pictures to display

Door FL, Dent(s), Acceptable 0,00

No pictures to display

Wing RR, Scratch(es), It - Spot repair 127,12



Alloy rim RR, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim FL, Scratch(es), LI - Repair and paint (complete) 114,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display